

22 May 2014

IMPORTANT INFORMATION

Defective Isolators Warning Issued by Energy Safety 21 May 2014

Carbon Footie is aware that a warning has been issued by Energy Safety, an Agency of the WA Department of Commerce, regarding defective models of Isolators which are used on PV Solar Systems. Carbon Footie is taking all appropriate measures to ensure our PV Solar installations are fully compliant and safe.

Please note the defective notice applies to a very small number of Isolators and is specific to model numbers only.

The defective brands and models include:

- 'Avanco' branded dc isolators (model numbers AV/DC4P25A, AV/DC2P25A, AV/DC4P25AUB, AV/DC2P625AU, AV/DC2P25AU, AV/DC2/2P25AU, AV/DC2/2P125AU, AV/DC4P25AU, AV/DC4P25AUS, and AV/DC4P25AUT).
- All "PVPower" branded dc isolators.
- GEN3 and SPM branded rotary type DC isolators model numbers: GEN3DC-25, GEN3DC-32, SPMDCISO-25A and SPMDCISO-32A.